



1




- |                |          |          |          |                  |          |          |          |          |           |           |           |           |
|----------------|----------|----------|----------|------------------|----------|----------|----------|----------|-----------|-----------|-----------|-----------|
|                |          |          |          |                  |          |          |          |          |           |           |           |           |
| <b>1</b>       | <b>2</b> | <b>3</b> | <b>4</b> | <b>5</b>         | <b>6</b> | <b>7</b> | <b>8</b> | <b>9</b> | <b>10</b> | <b>11</b> | <b>12</b> | <b>13</b> |
| confirmat 5x50 | 8x30     | 4x16     | 6,2x10,5 | 3,5x20<br>3,5x25 | 4x35     | M4x42    | 28-36    | 1x20     | 34x5      | 15x13     | 3mm       | 5mm       |


2




3




4




5




6




7




8




9




10




11




12




13




14



15




16







21




22




23




24




25



26



27



28

